	Туре	L#	Hits	Search Text	DBs	Time Stamp	Comm ents
1	BRS	L1	1	"5929577".pn.	USP AT	2005/11/ 30 16:50	
2	BRS	L2	1020 1	"20" adj khz	USP AT	2005/11/ 30 16:51	
3	BRS	L3	「 ノ / フ×	pwm and motor and "318"/\$.ccls.	USP AT	2005/11/ 30 16:51	
4	BRS	L4	9152	brushless	USP AT	2005/11/ 30 16:51	
5	BRS	L5	50	2 and 3 and 4	USP AT	2005/11/ 30 16:51	
6	BRS	L6	2101 0	emf or bemf or cemf or electromotive	USP AT	2005/11/ 30 16:52	
7	BRS	L7	24	5 and 6	USP AT	2005/11/ 30 16:52	

	Туре	L#	Hits	Search Text	DBs	Time Stamp	Comm ents
1	BRS	L1	9152	brushless		2005/11/ 30 13:53	
2	BRS	L2	6394 54	motor ·		2005/11/ 30 13:53	
3	BRS	L3	n a za	(emf or bemf or cemf or electromotive).ab.		2005/11/ 30 13:54	
4	BRS	L4	3497 78	position.ab.		2005/11/ 30 13:55	
5	BRS	L5	1	pwm or pulse adj width adj modulat\$5		2005/11/ 30 13:55	
6	BRS	L6	50	1 and 2 and 3 and 4 and 5		2005/11/ 30 13:55	

	Туре	L#	Hits	Search Text	DBs	Time Stamp	Comm ents
1	BRS	L1	9152	brushless	USP AT	2005/11/ 30 09:46	
2	BRS	L2	2832 3	single adj phase	USP AT	2005/11/ 30 09:47	
3	BRS	L3	3497 78	position.ab.	USP AT	2005/11/ 30 09:47	
4	BRS	L4	riuzu	(emf or cemf or bemf or electromotive).ab.	USP AT	2005/11/ 30 09:47	
5	BRS	L5	14	1 and 2 and 3 and 4	USP AT	2005/11/ 30 09:48	

	Туре	L#	Hits	Search Text	DBs	Time Stamp	Comm ents
1	BRS	L1	1	(emf or bemf or cemf or electromotive adj force).ab.	USP AT	2005/11/ 30 08:46	
2	BRS	L2	115/	momentar\$4 near3 interrupt\$4.ab.	USP AT	2005/11/ 30 08:48	
3	BRS	L3	9152	brushless	USP AT	2005/11/ 30 08:48	
4	BRS	L4	0	1 and 2 and 3	USP AT	2005/11/ 30 08:49	
5	BRS	L5	0	(switching or turning) adj2 off adj2 all adj2 (transistors or switches)	USP AT	2005/11/ 30 08:50	
6	BRS	L6	T / / ×	off near3 (transistors or switches).ab.	USP AT	2005/11/ 30 08:50	
7	BRS	L7	2	1 and 3 and 6	USP AT	2005/11/ 30 08:50	